

# Application Notice / Avis d'utilisation /

## Volkswagen, Porsche, SAAB Hard/No Start Condition Starter Installation Notice

Some early model Volkswagen, Porsche and SAAB vehicles may experience a condition where the starter motor cranks slowly or not at all upon activation of the ignition switch.

If, after installing this replacement starter, your vehicle still exhibits a hard start condition, it is suggested that you inspect the condition of the vehicle's electrical system for:

- Overall wire quality and integrity (i.e., terminal connections clean and tight, cracked insulation)
- Battery voltage
- The presence of all factory supplied heat shields

On these vehicles, a minimum of 9 volts is required to activate the starter solenoid.

Depending upon the overall condition of the vehicle's electrical system, it may be necessary to install a relay kit (Bosch Pt. #WR1) to provide adequate voltage to the starter solenoid.

## Volkswagen, Por Problème de dém difficile/non dém Avis d'installatio démarrageur

Certains anciens véhicules Vol  
SAAB peuvent avoir un problè  
démarrageur fait tourner le moteu  
du tout lorsque l'on met le con

Si le véhicule continue à avoir  
démarrer après l'installation du  
on suggère d'examiner l'état du  
véhicule pour vérifier:

- La qualité et l'intégrité gé  
connexions sont propres  
de la gaine des fils).
- La tension de la batterie.
- La présence de tous les él  
fournis à l'usine.

Il faut un minimum de 9 volts  
du démarreur de ces véhicules

Selon l'état global du système  
il peut être nécessaire d'install  
(no de pièce Bosch WR1) pour  
adéquate au solénoïde du dém