



Seepage rust with more likely below.



The Battery shelf and the “hell hole” (pinch and zoom) isn’t too bad, but definitely could use attention.

Surface rust - not too deep (primer above in the rear trunk)



The worst I found - creeping moisture from carpet, now removed - All new roof and roof sides to windshield seal solved the cab leaks. New tail light/license seals in the back stopped this too.

By far the worst is here below
the hell hole - planned on
replacing decorate rocker
covers.



The left rocker is shot, but spared
the unibody. Left side is fine.





No rust at front firewall in the front trunk - the washer/spare tire still works!!



Front trunk is fairly rust free







Have new hinge plate, threads and bolt ready to replace damaged left rear trunk hinge - all others OK.